

160469

.....JOURNAL...II.....
EVERDURE INC., AEROSOLIZER.....
ROUTE 1, BOX 468
RAPIDAN, CRADDOCK COUNTY, VIRGINIA
ATTENTION: GREGG CRISLICK

II. SITUATION: (AS OF TUESDAY, MARCH 23, 1993 2:00 P. HOURS)

A. ON-SITE COORDINATOR (OSC) AND TECHNICAL ASSISTANCE TEAM (PAT) ON SITE TO ASSESS THE ABANDONED EVERDURE INCORPORATED WOOD TREATING FACILITY TO DETERMINE WHETHER THERE IS A SUBSTANTIAL THREAT TO HUMAN HEALTH SAFETY AND THE ENVIRONMENT.

B. WEATHER: OVERCAST AND RAIN WITH TEMPERATURES IN HIGH 40'S

C. PERSONNEL ON SITE: ERV-1, PAT-3.

III. ACTIVITIES TAKEN

A. OSC AND PAT MET WITH ANGUS McDONALD AND WIFE, GRANDCHILDREN TO LAND OWNER JAMY McDONALD, TO DISCUSS HISTORY OF THE EVERDURE SITE. EVERDURE WAS A WOOD TREATING FACILITY THAT WAS IN OPERATION FROM APPROXIMATELY 1955 TO 1988. THE PRIMARY CHEMICALS USED IN THE WOOD TREATING PROCESS WERE CCA, AND ARSENIC ACID. A PARTIAL CLEANUP WAS CONDUCTED BY BOO FLO, WHICH REMOVED ARRS (38) DEFORMING 30 GALLON DRUMS LABELED ARSENIC ACID (17) 30 GALLON DRUMS LABELED CCA, AND (6) VARIOUS SIZE CONTAINERS UNLABELED. THERE ARE ALSO (9) CONCRETE BAMES WITH RESIDUAL SLUDGE.

B. PAT CONDUCTED SOIL SAMPLING INSIDE AND AROUND THE WOOD TREATING BUILDING. WATER SAMPLES WERE COLLECTED FROM THREE WELLS IN THE VICINITY OF THE FACILITY AS WELL AS FROM STANDING PUDDLES INSIDE THE BUILDING, RUNOFF STREAM, AND A NEAR BY FISHING POND. A TOTAL OF 3 SOIL SAMPLES WERE TAKEN FROM INSIDE THE BUILDING, 1 SAMPLE OF SLUDGE FROM THE BAMES, 3 SOIL SAMPLES WERE TAKEN OUTSIDE THE FACILITY, 3 WELL SAMPLES WERE TAKEN, 1 STANDING PUDDLE SAMPLE WAS TAKEN FROM INSIDE THE BUILDING, AND 1 POND SAMPLE WAS TAKEN FROM NEARBY FISHING POND.

III. FUTURE ACTIONS

A. FUTURE ACTIONS TO BE DETERMINED PENDING ANALYTICAL RESULTS OF SOIL AND WATER SAMPLES.

B. OSC TO REMAIN IN CONTACT WITH STATE AND LOCAL OFFICIALS.

KEVIN KOOB, OSC
U.S. EPA - REGION III, PHILA, PA

APR 10 1993

REC